
Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-135	Smoke	10/13/2008	ADS/TM	S11MM_008MH	Dry	Yes	1,458.28

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S11MM_032G1	S11MM_032MH	S11MM_012MH	52.30703	10
S11MM_048G1	S11MM_048MH	S11MM_032MH	197.7292	10
S11MM_060G1	S11MM_060DE	S11MM_045MH	42.27047	8
S11MM_014G1	S11MM_014MH	S11MM_047MH	44.62147	8
S11MM_047G1	S11MM_047MH	S11MM_008MH	48.07381	8
S11MM_044G1	S11MM_044MH	S11MM_012MH	198.1286	8
S11MM_045G1	S11MM_045MH	S11MM_047MH	279.0617	8
S11MM_012G1	S11MM_012MH	S13MM_031MH	452.8153	10
S11MM_008G1	S11MM_008MH	S11MM_044MH	143.2682	8

Observations & Photos

Obs_ID S1028-135-OB01

Address 2315 Longwood St

Status Private

Source Cleanout

Location Yard - front

Nearest MH S11MM_044MH

Comments Smoke from cleanout in front yard. 2315 Longwood St.



Picture \S1028-135-OB01-P01.jpg

Comments Front of house, 2315 Longwood St.